
220
110
AC100/120V 50/60HZ
GND
DRIVER/SENSOR
FUSE
MOTOR 2
MOTOR 1


205




SIGMA TECH
DRIVER 1
POWER
DRIVER 2
MOTOR DRIVER